

[illegible]

- [illegible]

THIS DRAINAGE PLAN IS BASED
ON SURVEY INFORMATION
PROVIDED BY:
RASCH & HYDE LTD.
ONTARIO LAND SURVEYORS
P.O. BOX C, 1335 HIGHWAY #3
EAST, UNIT B
DUNNVILLE, ON, N1A 2E1
TEL. (905) 774-7166

SURVEY No.		
1	FOR ALL FURN. UPGRADES	NOVEMBER 88
2	FOR ALL FURN. REPAIRS	DEC 20 1988
3	REPAIR FOR EQUIPMENT	NOVEMBER 88
4	REPAIR FOR ELEC.	DEC 20 1988
5	REPAIR FOR ELEC.	NOVEMBER 88
6	REPAIR FOR ELEC.	NOVEMBER 88
7	REPAIR FOR ELEC.	NOVEMBER 88
8	REPAIR FOR ELEC.	NOVEMBER 88
9	REPAIR FOR ELEC.	NOVEMBER 88

WEST NADALA AGRICULTURAL
SOCIETY

SITE SERVICE
PLAN

7402 MID ST.
BEANSVILLE, OH
106 1002

PROPOSED SITE
PLAN

EXISTING CEMENT - ARE NORTH - SHOWN PAVING

DATE: 10/24/2019

BY: C-1